



# Cactus Approved Sub-Supplier List

Name	Approved Process	Address
Houston Plating & Coatings	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014 CCS-612 Phosphorous Nickel	1301 Georgia Street South Houston, TX 77587
Webco Coating Inc	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	1708 E Butcher Switch Road Lafayette, LA 70507
Plas-Tech Coatings Inc	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	1000 North 5 Points Road West Chester, PA 19380
Houston Unlimited	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	9400 Hwy 290 E Chappell Hill, TX 77426
Metal Coating Corporation	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	3700 Dunvale Road Houston, TX 77063
Progressive Metal Services	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052	4117 Meadow Lane Bossier City, LA 71111
S+S Industries	CST-800 Copper Plating CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	5614 Nunn Street Houston, TX 77087
Nitretex	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	12227 FM 529 Houston TX 77041
Guerrero Plating Technology	CST-800 Copper Plating	15005 Mintz Lane Houston, TX 77014
National Heat Treat	CST-811 Gas Nitriding Heat Treatment per Cactus Wellhead Specs	6923 Brittmoore Road Houston, TX 77041
Specialty Heat Treat Inc	Heat Treatment per Cactus Wellhead Specs	11307 West Little York Houston, TX 77041
LST Heat Treating	CHT-100 Gas Carburizing Heat Treatment per Cactus Wellhead Specs	8 Gum Valley Circle Longview, TX 75602
Bodycote Thermal Processing	Heat Treatment per Cactus Wellhead Specs	116 Southpark Road Lafayette, LA 70508
Houston Heat Treat	Heat Treatment per Cactus Wellhead Specs	13802 Chrisman Road Houston, TX 77039
K & D Heat Treat	Heat Treatment per Cactus Wellhead Specs	2115 Humble Westfield Houston, TX 77073
Lark Heat Treating	Heat Treatment per Cactus Wellhead Specs	6640 Mayard Road Houston, TX 77041
Magnum Metal Treating	Heat Treatment per Cactus Wellhead Specs	4400 North Frazier Street Conroe, TX 77039
Lone Star Heat Treating	Heat Treatment per Cactus Wellhead Specs	3939 Blaffer Street Houston, TX 77026
SEI Heat Treat	Heat Treatment per Cactus Wellhead Specs	6910 Fulton Houston, TX 77022
Total NDT	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material CNT-007 Radiography	1747 Willow Lake Drive White Oak, TX 75693

February 12, 2026



# Cactus Approved Sub-Supplier List

Name	Approved Process	Address
LTD NDT Service, LLC	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	4702 SW 20th Street Oklahoma City, OK 73128
Accu-Test Labs	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material Laboratory Metallurgical Testing	6722 Guhn Road Houston, TX 77040
Common Sense Inspection Inc	CNT-004 Magnetic Particle Testing	1295 East 1750 South Vernal, UT 84078
Acuren Inspection	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing	405 N Eastman Road Longview, TX 75601
Bilfinger Inc	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	510 LaFlamme Road Broussard, LA 70518
P & B Testing Inc	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material Laboratory Metallurgical Testing	6645 W Tidwell Road Houston, TX 77092
Peak NDT Solutions	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	515a Verot School Road Lafayette, LA 70508
Sound NDT Solutions	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing	9672 Pozos Lane Conroe, TX 77303
Pro-Mag Inspection	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing	173 Trinity Lane Gray, LA 70359
RCI NDT	CNT-002 Visible Liquid Penetrant Testing	2771 FM 3081 Willis, TX
Rite Inspection Services	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	8484 Breen Drive Houston, TX 77064
TEAM Industrial Servies	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	3875 West Cardinal Drive Beaumont, TX 77705
Tejas Testing & Inspection Inc	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	4935 Milwee Street Houston, TX 77095
RSC Inspection	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	214 Progressive Blvd Houma, LA 70360
Lone Star NDT	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	508 W Lewis St. Conroe, TX 77304

Revision History	
2/12/2026	Revise Houston Plating scope
12/1/2025	Addition of Lone Star NDT and RSC Inspection
6/2/2025	Addition of Nitretex and Guerrero Plating Technology
9/19/2024	Revise AccuTest NDE scope
10/19/2023	Remove inactive sub-suppliers, addition of National Heat Treat and Houston Unlimited
9/22/2023	Initial publication

February 12, 2026